

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number CAD008342784		2. Page 1 of 1		3. Emergency Response Phone 818-241-2844		4. Manifest Tracking Number 001187750 FLE					
		5. Generator's Name and Mailing Address AUTOMATION PLATING 927 THOMPSON AVE. GLENDALE, CA 91201 Generator's Phone: 818-241-2844								Generator's Site Address (if different than mailing address)			
GENERATOR		6. Transporter 1 Company Name INDUSTRIAL WASTE UTILIZATION INC.						U.S. EPA ID Number CAD980585293					
		7. Transporter 2 Company Name						U.S. EPA ID Number					
DESIGNATED FACILITY		8. Designated Facility Name and Site Address US ECOLOGY HWY 95 AT 11 Miles South of Beatty BEATTY, NV 89003 Facility's Phone: 775-553-2203						U.S. EPA ID Number NVT330010000					
TRANSPORTER		9a. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity		12. Unit Wt./Vol.		13. Waste Codes	
						No. Type							
		1. RQ, Hazardous waste, solid, n.o.s. (F008 filter cake)9 NA3077 III				27 DA		22		4		484 F008	
		2. 7				2000		2000		1		181	
		3.											
		4. 46,040 lbs											
DESIGNATED FACILITY		14. Special Handling Instructions and Additional Information 961 (11a)-F008 filter cake w/cadmium/zinc/ Approval #07-012-8936											
		15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
		Generator's/Offor's Printed/Typed Name Hector Rodriguez				Signature <i>[Signature]</i>				Month Day Year			
		16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.				Port of entry/exit:				Date leaving U.S.:			
		Transporter signature (for exports only):											
		17. Transporter Acknowledgment of Receipt of Materials											
DESIGNATED FACILITY		Transporter 1 Printed/Typed Name ELCID BAN				Signature <i>[Signature]</i>				Month Day Year 7/5/08			
		Transporter 2 Printed/Typed Name				Signature <i>[Signature]</i>				Month Day Year			
		18. Discrepancy											
		18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection											
		Manifest Reference Number:											
		18b. Alternate Facility (or Generator) U.S. EPA ID Number											
DESIGNATED FACILITY		Facility's Phone:											
		18c. Signature of Alternate Facility (or Generator)											
		19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
		1. 2. 3. 4.											
		20. Designated Facility Owner or Operator Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
		Printed/Typed Name				Signature				Month Day Year			